UI Bulletin #111

Subject: **Auxiliary Power Connections**

Models: Chevrolet Caprice PPV (w SEO K5S-auxiliary battery)

Model Years: 2011-2014

Date: January 08, 2013

Revision Date: August 12, 2013

ADVISORY:

Condition:

Improper electrical connections using the power studs on the Isolation Relay rather the provided power studs. Any added power circuit in the trunk electrical center should not utilize the studs on the isolation relay

Recommendation:

The Caprice PPV equipped with the auxiliary battery (SEO K5S) utilizes an isolation relay to protect the auxiliary battery from being discharged during engine starting. To eliminate the possibility of improper power tapping refer to the image below to identify the location of the proper power taps on vehicles equipped with the auxiliary battery (SEO K5S) which is located in the trunk of the vehicle directly behind the RH wheel.

Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.



Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.